



**Klohn Crippen Berger**

**Teck Metals Ltd.**

**Pinchi Lake Mine Tailings Storage Facility**

***2020 Annual Summary of Tailings Facility Performance***



Platinum  
member

M07728A36.730



November 2020

November 10, 2020

Teck Metals Ltd.  
Kimberley Operations  
Bag 2000  
Kimberley, British Columbia  
V1A 3E1

**Ms. Michelle Unger**  
**Mine Manager**

Dear Ms. Unger:


**Pinchi Lake Mine Tailings Storage Facility**  
**2020 Annual Summary of Tailings Facility Performance**

We are pleased to submit the 2020 Annual Summary of Tailings Facility Performance on the Pinchi Lake Mine Tailings Storage Facility.

Please contact us if you have any questions regarding this report.

Yours truly,

**KLOHN CRIPPEN BERGER LTD.**



Daniel Klassen, P.Eng.  
Project Manager

DK/CT: jc



# Teck Metals Ltd.

## Pinchi Lake Mine Tailings Storage Facility

### *2020 Annual Summary of Tailings Facility Performance*

## CLARIFICATIONS

This report is an instrument of service of Kohn Crippen Berger (KCB). The report has been prepared for the exclusive use of Teck Metals Ltd. (Client) for the specific application to the 2020 annual summary of tailings facility performance, and it may not be relied upon by any other party without KCB's written consent.

KCB has prepared this report in a manner consistent with the level of care, skill and diligence ordinarily provided by members of the same profession for projects of a similar nature at the time and place the services were rendered. KCB makes no warranty, express or implied.

Use of or reliance upon this instrument of service by the Client is subject to the following conditions:

1. The report is to be read in full, with sections or parts of the report relied upon in the context of the whole report.
2. The Executive Summary is a selection of key elements of the report. It does not include details needed for the proper application of the findings and recommendations in the report.
3. The observations, findings and conclusions in this report are based on observed factual data and conditions that existed at the time of the work and should not be relied upon to precisely represent conditions at any other time.
4. The report is based on information provided to KCB by the Client or by other parties on behalf of the client (Client-supplied information). KCB has not verified the correctness or accuracy of such information and makes no representations regarding its correctness or accuracy. KCB shall not be responsible to the Client for the consequences of any error or omission contained in Client-supplied information.
5. KCB should be consulted regarding the interpretation or application of the findings and recommendations in the report.

## EXECUTIVE SUMMARY

This report presents the 2020 annual summary of tailings facility performance for Teck Metals Ltd.'s (Teck) Pinchi Lake Mine Tailings Storage Facility (TSF) by Klobn Crippen Berger Ltd. (KCB). This report was prepared to fulfill the requirements of a Dam Safety Inspection (DSI) in the Health, Safety and Reclamation Code for Mines in British Columbia (HSRC) (MEM 2016, 2017). The annual inspection of the TSF facilities was conducted in August 2020 by the Engineer of Record, Bob Chambers, of KCB. Routine inspections were carried out in October 2019 and May 2020 by the Site Surveillance Officer, Mark Pokorski, of EcoFor.

This summary section is provided in accordance with the HSRC, and Teck's "Guideline for Tailings and Water Retaining Structures" (Teck 2019).

### Summary of Facility Description

Pinchi Lake Mine has been closed since 1975. Teck completed the reclamation/closure works for the TSF in 2011. The TSF and associated water management infrastructure include the following:

- An earthfill tailings dam: 3 m to 15 m high, approximately 1300 m long.
- A tailings impoundment containing approximately one million cubic metres of tailings. The impoundment is a dry facility with glacial till cover and vegetation on the tailings surface. There is no storage of water in the impoundment.
- A free-flowing, riprap lined open channel Closure Spillway.
- The Ed Creek Diversion Channel, which diverts Ed Creek away from the TSF.

### Summary of Key Hazards

KCB understands that Teck's long-term goal for all tailings facilities is to reach landform status with all potential failure modes that could result in catastrophic release of tailings and/or water being reduced to non-credible. The long-term goal for the Pinchi TSF is for all potential catastrophic failure modes to be non-credible based on Extreme consequence loading conditions. Evaluation of failure modes with respect to this goal is ongoing.

Key observations related to the potential hazards associated with the TSF are summarized as follows:

**Earthquakes:** The dam is located in a region of low seismicity, with a peak ground acceleration of 0.04 g for the 1/2500 annual exceedance probability earthquake. There is lacustrine clay in the foundation of the dam that may be susceptible to cyclic softening if there was sufficient earthquake loading. Simplified deformation and post-earthquake stability analyses were performed and show that the dam meets CDA guidelines for seismic stability (CDA 2014) and that the predicted seismic deformation is 10 cm, which indicates that the dam is expected to perform well under seismic loading (KCB 2017b). **Summary – no present concern and no long-term concern indicated.**

**Surface Erosion:** Ed Creek Diversion Channel was designed to convey the 1000-year flood event without erosion damage, but gradual weathering and breakage of the riprap has reduced its capacity.

A portion of the channel is approximately 10 m from the Tailings Dam, and damage to the riprap during an extreme flood event could initiate gradual erosion of the channel towards the dam. This is addressed through surveillance and maintenance, and erosion would not be allowed to progress to the point where it undermines the dam toe. Options for remediating the channel are also being investigated, including replacing the riprap and possibly realigning the channel away from the dam.

**Summary – no present concern; further evaluation recommended to address possible concerns over the long term.**

### Consequence Classification

Consequence classification is not related to the likelihood of a failure, but rather the potential impact resulting from a failure if it did occur. The downstream consequence classification of the TSF was reviewed in 2012 after the completion of the reclamation/closure works, and the Tailings Dam was classified as **Significant** based on the 2007 Dam Safety Guidelines published by the Canadian Dam Association (CDA 2007). The consequence classification was based on a simplified dam breach assessment, but it did not evaluate the credibility of the failure modes considered. A failure modes evaluation should be completed to determine whether there are any credible failure modes, and if so, would they result in uncontrolled release of tailings and water.

### Summary of Key Observations and Significant Changes

There has been no construction or any other significant changes to the TSF or associated water management infrastructure since the 2019 inspection.

There are six vibrating wire piezometers at three locations around the dam and fourteen survey monuments. Piezometers are read twice per year, and survey monuments are measured every ten years. There were no significant changes in the measurements made from these instruments in 2020, and the quantifiable performance objectives (QPOs) were met. Piezometer readings show seasonal fluctuations between spring and summer/fall. Survey monuments were last read in December 2016, and the readings were below the alert criteria and did not show ongoing movements. There is normally no storage of water in the TSF and no instrumentation for water level or flow monitoring.

Overall, the dam is in good condition with no significant changes observed, which indicates no changes to stability. A stability assessment of the Tailings Dam was performed in 2017, which concluded that the dam meets industry standard static and seismic stability design criteria (KCB 2017b).

### OMS Manual and EPRP

The OMS Manual, which includes the EPRP as an appendix, was updated in 2019. The EPRP has since been incorporated into the site-wide Mine Emergency Response Plan (MERP), and the OMS Manual should be updated to reference the MERP.

### Dam Safety Review

A Dam Safety Review (DSR) of the Pinchi Lake Mine TSF and associated water infrastructure was performed by SRK in 2018. There was appropriate engagement and input from the Engineer of Record. The report is being finalized. The HSRC (MEM 2016, 2017) requires that all tailings storage

facilities undergo a DSR every 5 years at minimum. To comply with the HSRC, the next DSR should be carried out in 2023.

### Summary of Recommendations

The deficiencies and recommendations related to dam safety are summarized in the following table. Aligned with the noted good condition of the facility and no observed or computed stability concerns, none of the issues are high priorities. The levels of priority assigned to each item in the table are based on priority ratings developed by Teck (and consistent with HSRC) as follows:

- Priority 1 A high probability or actual dam safety issue considered immediately dangerous to life, health or the environment, or a significant risk of regulatory enforcement.
- Priority 2 If not corrected could likely result in dam safety issues leading to injury, environmental impact or significant regulatory enforcement; or a repetitive deficiency that demonstrates a systematic breakdown of procedures.
- Priority 3 Single occurrences of deficiencies or non-conformances that alone would not be expected to result in dam safety issues.
- Priority 4 Best Management Practice as a suggestion for continuous improvement towards industry best practices that could further reduce potential risks.

As shown in the table, none of the issues are expected to result in a dam safety issue and are therefore considered “best practice” issues rather than urgent, dam safety items.

## Summary of Deficiencies and Recommendations

Structure	ID No.	Deficiency or Non Conformance	Applicable Regulation or OMS Reference	Recommended Action	Priority	Recommended Deadline/Status
<b>Previous Recommendations Ongoing</b>						
TSF	2019-01	The dam breach assessment performed in 2012 did not specifically assess potential consequences related to the on-site residence.	HSRC	The dam breach assessment should be updated to meet current state of practice.	3	The residents have moved offsite. Dam breach assessment to be conducted if required after 2020-01 is completed.
Ed Creek Diversion Channel	2019-02	The riprap along the Ed Creek Diversion Channel is undersized and is deteriorating due to weathering.	OMS Manual	An options assessment and conceptual design should be completed for upgrading the channel to meet erosion protection requirements. Since failure of the riprap would not immediately affect the dam, the risk to the dam in the interim is effectively managed through inspections and maintenance as per the OMS Manual, and there is no immediate concern for dam safety.	3	Initial options assessment complete. Additional options are being considered and will be assessed in 2021.
<b>2020 Recommendations</b>						
TSF	2020-01	The dam breach assessment performed in 2012 did not assess the credibility of the failure modes considered.	HSRC	A failure modes evaluation should be completed to determine whether there are any credible failure modes, and if so, would they result in uncontrolled release of tailings and water.	3	End of 2021
Ed Creek Diversion Channel	2020-02	The riprap along the Ed Creek Diversion Channel is undersized and is deteriorating due to weathering	OMS Manual	Select one or two preferred options for upgrading/replacing the existing Ed Creek Diversion Channel that will be advanced to a feasibility level design.	3	Q3 2022
TSF	2020-03	The OMS Manual includes a superseded version of the EPRP as an appendix.	HSRC	The OMS Manual should be updated to reference the Mine Emergency Response Plan.	3	End of 2021

## TABLE OF CONTENTS

CLARIFICATIONS .....	i
EXECUTIVE SUMMARY .....	ii
<b>1 INTRODUCTION .....</b>	<b>1</b>
1.1 Purpose, Scope of Work and Methodology .....	1
1.2 Regulatory Requirements .....	1
1.3 Roles and Responsibilities .....	1
1.4 Facility Description .....	1
1.5 Background Information and History .....	2
1.5.1 General .....	2
1.5.2 Pre-2010 Construction .....	2
1.5.3 2010 and 2011 Reclamation/Closure Works .....	3
<b>2 SITE ACTIVITIES – FALL 2019 TO SUMMER 2020 .....</b>	<b>4</b>
<b>3 CLIMATE DATA AND WATER BALANCE DURING 2020 .....</b>	<b>5</b>
3.1 Climate Data .....	5
3.2 Water Balance .....	6
3.3 Water Quality .....	6
<b>4 SITE OBSERVATIONS – AUGUST 2020 .....</b>	<b>7</b>
4.1 Visual Inspection .....	7
4.1.1 Tailings Storage Facility .....	7
4.1.2 Borrow Area A Slope .....	9
4.1.3 Ed Creek .....	9
4.2 Instrumentation Review .....	10
4.2.1 Tailings Dam Instrumentation .....	10
4.2.2 Flow and Water Level Measurements .....	11
4.2.3 Survey Monuments .....	11
<b>5 DAM SAFETY ASSESSMENT .....</b>	<b>12</b>
5.1 Design Basis Review .....	12
5.2 Dam Safety Review .....	12
5.3 Failure Modes Review .....	12
5.4 Dam Classification Review .....	14
5.6 Operational Performance .....	17
5.7 OMS Manual and EPRP Review .....	17
<b>6 CONCLUSIONS AND RECOMMENDATIONS .....</b>	<b>18</b>
<b>7 CLOSING .....</b>	<b>20</b>
<b>REFERENCES .....</b>	<b>21</b>

## TABLE OF CONTENTS

(continued)

### List of Tables

Table 3.1	Fort St. James (No. 1092975) Temperatures and Precipitation – September 2019 to August 2020 vs. Normal Values.....	5
Table 4.1	Fall 2019 to Summer 2020 Piezometer Readings .....	10
Table 5.1	Comparison of CDA and HSRC Design Criteria for Tailings Dams Classified as Significant.....	12
Table 6.1	Summary of Deficiencies and Recommendations.....	19

### List of Figures

Figure 1.1	Mine Site Plan
Figure 1.2	Tailings Storage Facility – Plan
Figure 1.3	Tailings Storage Facility – Dam Cross Sections
Figure 4.1	August 2020 Observation Locations
Figure 4.2	Piezometer Readings

### List of Appendices

Appendix I	Facility Data Sheet
Appendix II	August 2020 Photographs
Appendix III	August 2020 Inspection Forms
Appendix IV	1975 Tailings Dam Drawing
Appendix V	Water Balance
Appendix VI	Quantifiable Performance Objectives



## 1 INTRODUCTION

### 1.1 Purpose, Scope of Work and Methodology

This report presents the 2020 annual summary of tailings facility performance for Teck Metals Ltd.'s Pinchi Lake Mine Tailings Storage Facility (TSF) by Klohn Crippen Berger Ltd. (KCB). This report was prepared to fulfill the requirements of a Dam Safety Inspection (DSI) in the Health, Safety and Reclamation Code for Mines in British Columbia (HSRC) (MEM 2016, 2017). The following activities were undertaken by KCB:

- Site inspections by Mr. Bob Chambers, P.Eng. (the Engineer of Record) and Mr. Daniel Klassen, P.Eng. on August 11 and 12, 2020.
- Review and update of the list of outstanding recommendations from the previous annual performance reports.
- Review instrumentation and confirm that readings are within acceptable limits.

KCB was accompanied by Mr. Jason McBain, P.Eng. (Teck) and Mr. Mark Pokorski, R.P.Bio. (Ecofor Consulting Ltd.). Mr. Pokorski conducted the spring inspection of the TSF and associated facilities.

The inspection was conducted and this report prepared in accordance with the Teck Guideline for Tailings and Water Retaining Structures (Teck 2019).

The annual performance report is issued before the end of the calendar year, so the period considered for climate data and instrumentation is from September 2019 to August 2020.

### 1.2 Regulatory Requirements

This inspection report addresses the performance of the TSF and associated water management infrastructure in accordance with the HSRC and the Permit Amendment Approving Closure Plan (Permit No. M-5) dated July 12, 2010.

### 1.3 Roles and Responsibilities

The HSRC describes and defines responsibilities for several key roles for a TSF (MEM 2016). For Pinchi TSF the following personnel fill these roles:

- Mine Manager: Ms. Michelle Unger of Teck
- TSF Qualified Person: Mr. Jason McBain, P.Eng., of Teck
- Engineer of Record: Mr. Bob Chambers, P.Eng., of KCB

### 1.4 Facility Description

The Pinchi Lake Mine is located in central British Columbia on the northern shore of Pinchi Lake approximately 25 km northwest of Fort St. James and 75 km northwest of Vanderhoof. Pinchi Lake is long (23 km) and narrow (ranging from approximately 1000 m to 3250 m wide) and lies at an

elevation of approximately 720 metres above sea level (masl). At the mine site, Pinchi Lake is only 1250 m wide. The terrain near the mine site is heavily wooded with rolling hills and generally less than 300 m of relief, although some hills rise to over 1000 masl.

The mine was originally commissioned in the 1940s and operated from 1940 to 1944 during the Second World War. The mine was closed until 1968, when it re-opened and operated from 1968 to 1975. The property was placed on care and maintenance in 1975. Teck substantially completed the mine reclamation and closure works from 2010 to 2012.

A mine site plan and the general arrangement of the TSF are presented in Figures 1.1 and 1.2, respectively. Cross-sections of the Tailings Dam, based on 2012 topography, are shown in Figure 1.3.

The Pinchi Lake Mine TSF was constructed in 1967 and utilized between 1967 and 1975. The TSF is a side hill impoundment covering approximately 24 ha and contained on three sides by an embankment dam. Approximately one million cubic metres of tailings are stored in the TSF. The Tailings Dam is approximately 1300 m long, and 3 m to 15 m high. The original dam was designed and constructed in the late 1960s, and was raised in 1975 as shown in the historical drawing presented in Appendix IV. The dam was originally a homogeneous dam constructed with local glacial till and upstream slopes of 2.0H:1V near the crest and 2.5H:1V elsewhere, and downstream slopes of 2.0H:1V near the crest and 3.0H:1V elsewhere. When the dam was raised in 1975, a zone of rockfill was placed on the downstream slope with a transition zone between the glacial till and the rockfill.

Ed Creek originally flowed through the impoundment area as shown in the drawing in Appendix IV (labelled as “Main Creek” and “Ed Main Creek” in the drawing). The creek was diverted to Pinchi Lake via the Ed Creek Diversion Channel, which was constructed on the east side of the TSF (see Figure 1.2).

Water management for the TSF, prior to the implementation of the reclamation/closure works in 2010, comprised a low level decant system supplemented by an open channel Emergency Spillway. The decant box and spillway were located near the west abutment of the Tailings Dam as shown in the drawing in Appendix IV. The decant box and the spillway are labelled in the drawing as “new water collection box” and “overflow ditch”, respectively. The decant system and the Emergency Spillway were decommissioned, and a Closure Spillway was constructed, as part of the closure works completed by Teck in 2010 and 2011.

A facility data sheet that summarizes key information for the TSF is presented in Appendix I.

## **1.5 Background Information and History**

### **1.5.1 General**

The design and construction history, from start-up to closure, is summarized below.

### **1.5.2 Pre-2010 Construction**

The design/construction chronology was as follows:

- 1967 engineering of the facility (Stage 1) by Ripley, Klohn and Leonoff;
- 1967 construction under Kootenay Engineering inspection with Tara Engineering Laboratories carrying out fill placement quality control;
- 1971 inspection letter from Cominco Civil Designer noting settlement (approximately 2 ft) and resulting loss of freeboard - remedial measures were suggested;
- 1974 engineering report by Golder Associates for a 10 ft dam raise (Stage 2);
- 1975 letter by Golder Associates approving design drawings for a reduced dam raise of 5 ft;
- 1975 construction of the 5 ft raise;
- 2000 stabilization and rehabilitation of the Ed Creek Diversion Channel;
- 2001 rehabilitation of the Ed Creek Diversion Channel as the riprap and fish habitat were eroded by a large flood wave that resulted from a series of beaver dam failures; and
- 2001 Emergency Spillway excavation to increase flow capacity.

### 1.5.3 2010 and 2011 Reclamation/Closure Works

The following reclamation/closure works for the TSF were completed by Teck in 2010 and 2011:

- drained the water from the Tailings Impoundment;
- abandoned the Emergency Spillway;
- abandoned the decant system and backfilled the concrete decant inlet box with soil;
- placed and seeded soil cover over the tailings in the TSF;
- trimmed the crest of the western leg of the Tailings Dam for use as cover material for the tailings; and
- constructed the TSF Closure Spillway.

In addition to trimming the TSF dam crest for the 2010/2011 closure works, Teck developed three borrow areas adjacent to the TSF as a source of cover material for the tailings (see Figure 1.2): Borrow Area A is located downstream of the south leg of the Tailings Dam and Borrow Areas B and C are located upstream of the TSF.

The Closure Spillway is located in the area of the former supernatant pond. The spillway invert is set such that water would not be stored in the Tailings Impoundment under normal conditions. Draining of the water from the impoundment and constructing the spillway has converted the TSF into a “dry” facility.

## **2 SITE ACTIVITIES – FALL 2019 TO SUMMER 2020**

The TSF is a closed facility and does not require operational intervention. Scheduled and event driven inspections and maintenance work are carried out on an as-required basis. Requirements for routine inspection and monitoring, and trigger levels for inspection following an extreme event are presented in the Operation, Maintenance and Surveillance (OMS) Manual (KCB 2019a).

The Site Surveillance Officer, Mr. Mark Pokorski, carries out inspections of the facility twice per year: one in the spring after freshet, and one in the fall. The 2019 fall inspection was carried out on October 23, 2019, and the 2020 spring inspection was carried out on May 14, 2020. These inspections did not identify any dam safety issues. The 2020 fall inspection was performed on November 9, 2020, and reporting was in progress at the time of writing this annual performance report.

An annual inspection of the TSF is conducted by the Engineer of Record; this inspection occurred on August 11 and 12, 2020.

Clearing of vegetation was performed on the slopes of the dam and in Ed Creek Diversion Channel in fall 2019.

Apart from these routine inspections and site maintenance, there were no other site activities during 2020.

### 3 CLIMATE DATA AND WATER BALANCE DURING 2020

#### 3.1 Climate Data

There is no climate station at the mine site; however, temperature and precipitation data for Fort St. James (Environment Canada climate station no. 1092975, located approximately 25 km southeast of the mine) were reviewed. Table 3.1 presents a comparison of the recorded monthly temperatures and precipitation from Sep. 1, 2019 to Aug. 31, 2020 with the station's temperature and precipitation normals for 1981 to 2010. The records of temperature and total precipitation (rainfall + snowfall) from this station are fairly complete, but separate measurements of rain and snow are not available at this or any other nearby stations with recent data.

The climate data shows that temperatures and precipitation during the period examined were close to average conditions.

**Table 3.1 Fort St. James (No. 1092975) Temperatures and Precipitation – September 2019 to August 2020 vs. Normal Values**

	Sep	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Year
<b>1981-2010 Normals</b>													
<b>Temperature</b>													
Daily Average (°C)	10.2	4.3	-3.0	-7.8	-9.5	-6.8	-1.8	3.9	9.2	13.4	15.4	14.8	3.5
Daily Maximum (°C)	16.4	9.0	0.6	-3.8	-5.3	-1.7	4.0	9.9	15.6	19.6	21.8	21.7	9.0
Daily Minimum (°C)	3.9	-0.5	-6.5	-11.7	-13.7	-11.8	-7.7	-2.2	2.8	7.2	8.9	7.9	-2.0
<b>Precipitation</b>													
Rainfall (mm)	39.1	38.7	15.7	4.2	4.9	3.6	5.9	18.0	38.2	50.6	50.6	45.0	314.5
Snowfall (cm)	0.2	9.5	28.8	38.4	43.3	26.4	19.8	5.7	0.7	0.0	0.0	0.0	172.7
Precipitation (mm)	39.3	48.1	44.5	42.6	48.1	30.0	25.7	23.7	38.9	50.6	50.6	45.0	487.2
<b>September 2019 – August 2020</b>													
<b>Temperature</b>													
Daily Average (°C)	11.5	3.9	-0.8	-5.6	-8.5	-3.2	-3.1	1.7	10.7	12.3	14.8	14.5	4.0
Daily Maximum (°C)	16.3	8.3	3.2	-2.4	-3.5	2.1	2.9	8.3	17.0	17.5	19.7	19.4	9.1
Daily Minimum (°C)	6.7	-0.4	-4.8	-8.8	-13.6	-8.4	-9.1	-4.8	4.4	7.1	9.9	9.6	-1.0
<b>Precipitation</b>													
Rainfall (mm)	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Snowfall (cm)	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Precipitation (mm)	32.4	43.2	39.5	29.2	60.4	25.2	16.8	7.5	19.2	45.5	68.5	48.1	435.5
<b>No. of days of missing data</b>	1	1	0	1	3	2	0	0	1	0	0	0	9

### **3.2 Water Balance**

The HSRC (MEM 2016, 2017) calls for a water balance review. Since the Pinchi Lake Mine TSF is a dry facility, there is no storage of water in the Tailings Impoundment and stormwater inflows are passively released from the impoundment via the Closure Spillway. Based on observations, there has been no indication of water ponding behind the spillway, except in small local depressions in the tailings cover. Because inflow to the impoundment is limited to direct precipitation and stormwater runoff from small catchments upslope of the TSF, an annual water balance review is deemed to be unnecessary. However, a water balance was prepared in 2019 based on average precipitation from 1998 to 2017 at Fort St. James (Environment Canada climate station no. 1092970). The water balance is included in Appendix V. The average discharge through the spillway was estimated to be 0.5 L/s.

### **3.3 Water Quality**

The surface water quality discharging from the TSF is currently monitored annually under effluent permit PE-224. The groundwater quality at Pinchi Lake Mine is currently monitored under the Contaminated Sites Regulation (B.C. Reg. 375/96). Both surface and groundwater quality are reported by Teck to B.C. Ministry of Environment and B.C. Ministry of Energy, Mines & Petroleum Resources.

## 4 SITE OBSERVATIONS – AUGUST 2020

### 4.1 Visual Inspection

The following areas were inspected during the August 11 to 12, 2020 site visit:

- Tailings Storage Facility:
  - ◆ Tailings Impoundment (drained and covered with soil);
  - ◆ Tailings Dam; and
  - ◆ Closure Spillway.
- Borrow Area A Slope;
- Ed Creek:
  - ◆ Ed Creek Diversion Channel; and
  - ◆ Ed Creek culverts under Pinchi Lake Road.

Weather during the site visit was cloudy with light showers, and about 12°C. Site observations and recommendations are presented in the following sub-sections. Observation locations referred to in the following sub-sections are identified in Figure 4.1. Selected photographs taken during the inspection are presented in Appendix II, and inspection forms are presented in Appendix III.

#### 4.1.1 Tailings Storage Facility

##### Tailings Impoundment

- There was no flowing or standing water in the Tailings Impoundment at the time of inspection. In previous inspections, a small pond on the south side of the Closure Spillway has been observed, but this area was dry at the time of the inspection.
- The soil cover on the tailings is covered in grass (Photos II-5 and II-7 in Appendix II). A detailed inspection of the cover was not conducted as it was not a part of the scope of the annual inspection.
- In 2014, Teck placed riprap at a location on the cover where flow was observed entering the Closure Spillway (Location 2 in Figure 4.1; Photos II-16 to II-17). The riprap appears to be performing well.

##### Tailings Dam

- The dam crest, and upstream and downstream slopes of the Tailings Dam appeared to be in good condition.
- No cracks were observed on the dam crest. Longitudinal cracks were previously observed on the crest of the southwest leg of the Tailings Dam in 2015, 2017, 2018, and 2019, but these were not visible at the time of the inspection. The cracks are likely surficial features related to drying of the dam crest surface and are not a dam safety concern. Weather conditions

recorded in Fort St. James prior to the inspection showed small amounts of rainfall nearly every day in early August, and the grass was wet at the time of the inspection; thus, the surface of the dam crest was likely moist and this may be why the cracks were not observed.

- The dam slopes were covered with grasses and small shrubs. Larger vegetation including some trees were cleared from the east leg of the dam in fall 2019. Some bushes had since regrown in this area (Photo II-1) but were within the 1.5 metre height limit recommended in the vegetation management plan (Spectrum 2017).
- A pond was observed in the trees near the toe of the east leg of the Tailings Dam (see Figure 1.2 for location; Photo II-2) as in previous inspections. This pond is located near a drainage channel that was shown on historical drawings of the TSF (see Appendix IV) and labelled “runoff channel.” The channel ran parallel to the main Ed Creek channel, and apparently once joined up with Ed Creek just inside the TSF. The pond appears to collect local runoff, and it drains through a channel to the south and through a culvert into Ed Creek Diversion Channel.
- Apart from the pond noted above, the ground at the downstream toe of the dam was dry and no ponded water or seepage were observed.

### Closure Spillway

- There was no flow or standing water in the Closure Spillway channel; there was a 30 cm deep pond at the downstream end of the riprap (Photo II-24).
- The riprap along the entire Closure Spillway channel appeared to be in good condition (Photos II-16 to II-22, and II-24). The spillway has likely not experienced any high flood discharges since it was constructed. Vegetation growth in the channel was minimal, only a few small shrubs (Photo II-22).
- A small slump in the slope above the riprap on the right (north) side of the spillway channel has been noted in inspections since 2014 (Location 1 in Figure 4.1). The slump area was covered in grass and the head scarp was only visible at close range (Photo II-23). The upstream side of the slump is about 90 m downstream of the dam centreline. The condition of the slump has not noticeably changed in the last six years, and it is not expected to impact the Tailings Dam or the performance of the spillway.
- The spillway downstream channel was observed at the culvert crossing on the road adjacent to the Emergency Spills Lagoon (Photos II-25 to II-27). The middle reach immediately upstream of the culvert appeared to be in good condition. Tall grasses and cattails were growing in the channel but were within the 1.5 metre height limit recommended in the vegetation management plan (Spectrum 2017). There was grass growing in front of the culvert inlet, partially blocking it. There was no flow into the culvert at the time of the inspection. The outlet of the culvert was clear of vegetation, but there was water ponding locally at the outlet to 5 cm above the invert (Photo II-26). The culvert is not related to dam safety but clearing of the inlet may be prudent to restore its normal flow capacity. The lower reach of the spillway



downstream channel appeared to be in good condition, although there were some larger bushes growing that were close to 1.5 m high (Photo II-27).

#### 4.1.2 Borrow Area A Slope

- Borrow Area A is located near the south leg of the Tailings Dam. The slope, which is about 10 m downstream of the toe, appeared to be in good condition (Photos II-28, II-30 and II-33).
- Cracks were observed on the slope from 2013 to 2017 (Location 3 in Figure 4.1). Measurements of crack movements were taken from 2015 to 2018 using metal rods installed on either side of the cracks (Photo II-29), but these measurements showed no ongoing movements and were discontinued in 2019. These cracks are no longer visible due to vegetation growth. However, newly discovered cracks were observed in the northeast corner of the borrow area (Location 4 in Figure 4.1, Photo II-32). These cracks are located about 20 m east of the eastern set of crack monitoring rods and are up to 2 cm wide and 10 cm deep. The borrow area slope is not very high in this corner (about 2 m), so even if these cracks led to slumping of the borrow area slope it would not retrogress to the dam. Therefore, these cracks are not a dam safety concern. Nevertheless, this area will continue to be monitored during routine inspections as per the OMS Manual.
- A few small areas of wet ground were observed starting in the northeast corner of the borrow area and moving slightly downhill to the west along the toe of the slope for 50 m (Location 5 in Figure 4.1; Photo II-31). No ponds larger than a few centimetres diameter were observed, and there was no flowing water. Similar wet areas have been observed since 2011, and they are believed to be associated with groundwater unrelated to the TSF. Outside of these wet areas, the ground on the slope and along the toe was dry.

#### 4.1.3 Ed Creek

##### Ed Creek Diversion Channel

- Vegetation was observed in the base of Ed Creek Diversion Channel, including tall grasses and some bushes, but it was not excessive (Photos II-34, and II-36 to II-44). The vegetation was cleared in this area in fall 2019 but it has quickly regrown.
- Previous annual performance reports have noted that the riprap along some areas of the Ed Creek Diversion Channel is weathering and breaking up (Photo II-35). The condition of the riprap appeared similar to previous inspections. Degradation of the riprap is discussed further in Section 5.5.

The riprap along a small section of the channel (Location 6 in Figure 4.1; Photo II-39), where a depression had formed in the riprap surface, was replaced in 2014. This riprap appeared to be in good condition.

- The 460 mm diameter HDPE culvert on the north bank of the Ed Creek Diversion Channel had some minor vegetation growing in front of the inlet (see Figure 1.2 for culvert location, and Photos II-45 and II-46). This is not a dam safety concern.

## Ed Creek Culverts Under Pinchi Lake Road

- There are two culverts on Ed Creek under Pinchi Lake Road east of the mine gate (see Figure 1.2 for location). Flow was observed in the east culvert only, with a depth of 70 mm at the inlet.
- There was no vegetation in front of the culvert inlets (Photo II-47).
- A ditch had recently been excavated along Pinchi Lake Road near the culvert inlets (Photo II-49).

## 4.2 Instrumentation Review

### 4.2.1 Tailings Dam Instrumentation

There are six vibrating wire piezometers at three locations around the dam (four piezometers at the toe, two at the crest) as shown in Figure 1.2; these piezometers are read twice per year at minimum. Quantifiable Performance Objectives (QPOs) for the piezometers are defined as threshold piezometric elevations, and these are given in Appendix VI.

Piezometer readings taken in fall 2019 to summer 2020 are included in Table 4.1, and threshold values are shown for comparison. The readings are all below the threshold values. The readings show that the phreatic surface is 1 m to 3 m below ground at the toe of the dam, and 10 m below the crest at the highest dam section. Piezometer readings are shown as elevations versus time in Figure 4.2. The readings in the piezometers at the dam toe (DH16-01-VWP1,2 and DH16-03-VWP1,2) show seasonal fluctuations up to 2 m, with higher readings in the spring and lower readings in the fall. The piezometers installed below the dam crest (DH16-02-VWP1,2) have shown less variation in the readings after an initial period of stabilization following installation.

Prior to the 2010/2011 closure works, a piezometer located 10 m from DH16-02-VWP1,2 showed typical readings of around El. 733.5 m, which is 1.2 m higher than the Aug. 12, 2020 reading. This suggests the piezometric levels in the dam have gone down compared to the condition before the pond was drained.

**Table 4.1 Fall 2019 to Summer 2020 Piezometer Readings**

Piezometer ID	Piezometric Elevation (m)				Depth Below Ground (m)		
	Threshold Value	Oct. 17, 2019	May 14, 2020	Aug. 12, 2020	Oct. 17, 2019	May 14, 2020	Aug. 12, 2020
DH16-01-VWP1	736.1	733.1	735.1	734.3	3.0	1.0	1.8
DH16-01-VWP2	736.1	733.2	734.2	733.9	2.9	1.9	2.2
DH16-02-VWP1	738.5	731.7	732.3	732.3	10.3	9.7	9.7
DH16-02-VWP2	738.5	731.8	732.5	732.5	10.2	9.5	9.5
DH16-03-VWP1	737.0	734.8	735.2	735.1	3.1	2.7	2.8
DH16-03-VWP2	737.0	734.7	735.1	735.0	3.2	2.8	2.9

#### **4.2.2 Flow and Water Level Measurements**

Since there is no pond, there is no flow measurement or water level instrumentation at the TSF. Prior to decommissioning, flow from the decant system was measured. Water is now released through the Closure Spillway but, given that the spillway channel is lined with large riprap, most of the low flows pass through the riprap, making it difficult to measure flow.

#### **4.2.3 Survey Monuments**

Survey monuments were installed on the Tailings Dam crest in 1998; however, some monuments were destroyed over the years. New survey monuments were installed in June 2014. The locations of the 2014 monuments and the surviving 1998 monuments are shown in Figure 1.2. QPOs for the survey monuments are provided in Appendix VI.

Readings were last taken in December 2016, and the readings met the QPOs and did not show ongoing movements (KCB 2017a). The survey monuments are to be read every ten years, so the next readings will be in 2026.

## 5 DAM SAFETY ASSESSMENT

### 5.1 Design Basis Review

The relevant design criteria from CDA (2014) and HSRC (MEM 2016, 2017) are compared in Table 5.1. The site conditions are being evaluated to confirm that the TSF meets design criteria for the Closure – Passive Care phase, as described by CDA (2014). The criteria in HSRC are similar to the CDA criteria for Closure – Passive Care.

**Table 5.1 Comparison of CDA and HSRC Design Criteria for Tailings Dams Classified as Significant**

Parameter	CDA (2014)		HSRC (MEM 2016, 2017)
	Construction, Operation, and Transition Phases	Closure – Passive Care Phase	
Annual Exceedance Probability (AEP) – Floods	Between 1/100 and 1/1000	1/3 between 1/1000 and PMF	1/3 between 1/975 and PMF
AEP – Earthquakes	Between 1/100 and 1/1000	1/2475	1/2475
Factor of safety for slope stability:			
Static, Long Term	1.5	1.5	1.5
Pseudostatic	1.0	1.0	Not specified
Post-Earthquake	1.2	1.2	Not specified
Steepest Allowable Downstream Slope	Not specified	Not specified	2H:1V

### 5.2 Dam Safety Review

A Dam Safety Review (DSR) of the Pinchi Lake Mine TSF and associated water infrastructure was performed by SRK in 2018. There was appropriate engagement and input from the Engineer of Record. The report is being finalized.

The HSRC (MEM 2016, 2017) requires that all tailings storage facilities undergo a DSR every 5 years at minimum. To comply with the HSRC, the next DSR should be carried out in 2023.

### 5.3 Failure Modes Review

KCB understands that Teck's long-term goal for all tailings facilities is to reach landform status with all potential failure modes that could result in catastrophic release of tailings and/or water being reduced to non-credible. The long-term goal for the Pinchi TSF is for all potential catastrophic failure modes to be non-credible based on Extreme consequence loading conditions. Evaluation of failure modes with respect to this goal is ongoing.

A summary of the current conditions is provided below to describe the safeguards that are in place and the justification that these failure modes are well-managed for the Pinchi TSF.

The potential failure modes included in the CDA Dam Safety Guidelines (2013) were reviewed based on the inspection and review of available documents:

- **Overtopping:** There is no permanent pond in the TSF, and the Closure Spillway is designed to convey flood flows passively without developing a large pond in the TSF. A hydrotechnical review of the Closure Spillway found that the freeboard in the TSF during the 1/3 between 1000-year and PMF event is over 4 m (KCB 2019b). The spillway and freeboard are effective controls to manage overtopping risks.
- **Internal Erosion and Piping:** The dam includes three fill zones: local silt-clay and glacial till borrow material, a rockfill zone on the downstream slope, and a transition material between the silt-clay/glacial till and the rockfill. The filter adequacy was reviewed previously, and it was found that the as-built information is insufficient to assess the filter compatibility of these materials (KCB 2015b). However, the observed performance of the dam, combined with the fact that the TSF is now a dry facility, provide evidence that the filter is functioning adequately to prevent piping. Seepage water or evidence of piping at the dam toe have not been observed during annual inspections. Since the pond was drained during the 2010 to 2011 closure works the seepage gradients through the dam have reduced, and this is reflected in lower piezometer readings in the dam compared to the pre-2010 readings, as discussed in Section 4.2.1. Checking the dam toe for seepage is included in the scheduled surveillance in the OMS Manual (KCB 2019a).
- **Slope Instability:** A stability assessment of the TSF was completed in 2017 (KCB 2017b) and found that the stability criteria described in Section 5.1 are met. The assessment included analyses using undrained strengths in the foundation clay. The condition of the dam is generally more favourable for stability now than it was during operations due to the draining of the pond and trimming of the dam crest in some areas. Survey monuments on the dam crest have not shown ongoing movements (Section 4.2.3).
- **Foundation Irregularities:** A drilling and laboratory testing program was carried out in 2016 to confirm whether silt or clay soils are present beneath the dam and to characterize their geotechnical properties (KCB 2017c). The investigation identified lacustrine clay below the west leg and the east leg of the dam, but the drill hole at the southwest leg of the dam, where the dam is highest, did not encounter lacustrine clay. The Borrow Area A slope has exposed foundation soils near the south leg of the dam and no lacustrine clay was visible, and earlier drill holes in this area confirm glacial till-like soils. The foundation investigation is believed to be sufficiently detailed for this facility. The stability assessment described above examined slip surfaces through the lacustrine clay and found that stability criteria were met.
- **Surface Erosion:** There are no significant erosion features on the crest or slopes of the dam. Surface runoff from the impoundment drains towards the closure spillway and will not erode the dam surface. The dam surface is vegetated and well protected against surface erosion. The downstream slope of the dam includes coarse rockfill, so any erosion channels that form would be self-armouring and unlikely to rapidly erode through the dam.

Ed Creek Diversion Channel was designed to convey the 1000-year flood event without erosion damage, but gradual weathering and breakage has reduced the riprap capacity. A portion of the channel is approximately 10 m from the Tailings Dam, and damage to the riprap during an extreme flood event could initiate gradual erosion of the channel towards the dam. This is addressed through surveillance and maintenance, and erosion would not be allowed to progress to the point where it undermines the dam toe. Options for remediating the channel are also being investigated, including replacing the riprap and possibly realigning the channel away from the dam.

- **Earthquakes:** The mine is in an area of low seismic activity, and the estimated seismic ground motions are small, with a peak ground acceleration (PGA) of 0.04 g for the 1/2500 AEP earthquake event for Site Class B/C (KCB 2020b). A simplified deformation analysis was performed as part of the stability assessment (KCB 2017b) using the Hynes-Griffin and Franklin (1984) method, and the predicted deformation was 10 cm, which indicates that the dam is expected to perform well under seismic loading. A post-earthquake stability analysis was also performed assuming full liquefaction of the tailings. Note that a liquefaction triggering analysis has never been performed for these tailings, but given the low PGA, full liquefaction of the tailings is likely a conservative assumption. The post-earthquake analysis met the minimum FOS of 1.2 recommended by CDA (2014), indicating that a flow-slide failure due to liquefaction of the tailings is unlikely. Note that both the deformation and post-earthquake analyses used 80% of the peak undrained strength in the lacustrine clay to account for cyclic softening, which is likely conservative given the low PGA.

## 5.4 Dam Classification Review

Consequence classification is not related to the likelihood of a failure, but rather the potential impact resulting from a failure if it did occur. As a follow-up on the completion of the reclamation/closure works, KCB reviewed the dam classification for the TSF in 2012 with respect to the criteria presented in the 2007 CDA Dam Safety Guidelines (CDA 2007), and the HSRC. Details of the classification review are presented in Pinchi Lake Mine Post-Reclamation Monitoring Requirements (KCB 2012), and the results are summarized below.

### CDA Dam Classification

KCB (2012) stated that the area downstream of the dam is undeveloped, with no settlements, public roads or any other infrastructure. There is no permanent population at risk. In the event of a breach at the Tailings Dam, releases from the impoundment could enter Pinchi Lake. The TSF was classified as Low for economic and cultural losses, and Significant for loss of life and environmental losses. Therefore, the overall classification of the Tailings Dam is Significant.

The 2012 classification review included a simplified dam breach assessment to estimate the peak discharge, tailings outflow volume and tailings runout distance for hypothetical sunny-day and rainy-day failure scenarios. These hypothetical scenarios were not evaluated to confirm that they are credible failure modes.

*Recommendation/Action:*

*A failure modes evaluation should be completed to determine whether there are any credible failure modes, and if so, would they result in uncontrolled release of tailings and water.*

The 2012 dam breach assessment also did not specifically address the presence of the on-site residence, which was occupied at the time, so an update to the assessment was planned to address this issue (recommendation 2019-01). However, the residents have since moved offsite, so this is no longer a concern. Therefore, the previously proposed updates to the dam breach assessment can be put on hold until after the failure modes evaluation is completed, and the need for an updated assessment can be re-evaluated at that time.

## HSRC Classification

All tailings storage facilities are required to have the consequence classification determined by the Engineer of Record in accordance with the CDA Dam Safety Guidelines (CDA 2013), as described above, and design criteria are given in the Code based on the consequence classification. Design criteria that are relevant to the Pinchi TSF are described in Section 5.1.

## 5.5 Physical Performance

### Geotechnical

The dam has performed adequately for over 40 years, and there is no record of slumping or instability since operations ceased in 1975. The closure works in 2010 and 2011 included changes that improved the stability of the dam, including:

- draining the pond, resulting in a decrease in phreatic levels within the dam (as discussed in Section 4.2.1); and
- trimming the crest of the west leg of the Tailings Dam, resulting in a reduction in driving forces for potential failure surfaces in that area.

Borrow Area A was excavated about 10 m from the toe of the south leg of the Tailings Dam during the closure works, and is therefore relevant to performance of the dam. Longitudinal cracks were identified on the north slope of Borrow Area A in August 2013. The stability of the overall slope (which includes the Tailings Dam) was reviewed in 2017 under static and seismic loadings, and was found to meet the design criteria summarized in Table 5.1 (KCB 2017b). However, localized slumping of the borrow area slope could occur and may impact the Tailings Dam if allowed to progress. Therefore, monitoring of the Borrow Area A slope for development of cracks, seeps and movement is part of regular surveillance as described in the OMS Manual (KCB 2019a).

A foundation investigation was performed in 2016 to confirm whether silt or clay soils are present beneath the dam and to characterize their geotechnical properties (KCB 2017c). The investigation concluded that lacustrine clay is present below portions of the dam. The strength of the clay was characterized through laboratory testing of sonic core samples. The data obtained during the



investigation was used to assess stability of the Tailings Dam, which concluded that the dam meets the static and seismic stability design criteria described in Section 5.1 (KCB 2017b).

### Hydrotechnical

The Closure Spillway is a free-flowing riprap-lined open channel, which passively releases water from the TSF. There is no storage of water in the TSF. The spillway is lined with large riprap and non-flood flows pass through the riprap with very little, if any, flow over the riprap surface. To the best of our knowledge, the Closure Spillway has not been subjected to any large flood flows since it was constructed in 2010.

The Closure Spillway was designed to route the 24-hour 1000-year rainfall plus 100-year snowmelt event (KCB 2009b). This design was adequate to meet CDA (2007) criteria, which specified the 1000-year flood event as the criteria for a Significant dam. CDA (2014) increased the criteria for Significant tailings dams in the Passive Care phase of closure to 1/3 between the 1000-year event and the Probable Maximum Flood (PMF), and HSRC (MEM 2016) set the criteria in all phases of the mine life to 1/3 between the 975-year event and the PMF (see Table 5.1 for a summary of the revised criteria). However, the HSRC states that the revised criteria do not apply when the chief inspector has received a permit application before the date when the criteria came into force, which is the case for the spillway. Nevertheless, an evaluation of the spillway capacity with respect to Closure – Passive Care criteria was completed (KCB 2019b), and this showed that the spillway can convey the higher design flows without overtopping, but the spillway channel riprap downstream of the dam toe would likely be damaged in the process. Options for upgrading the spillway are being investigated.

Ed Creek Diversion Channel was designed to convey the 1000-year flood event without erosion damage. The right bank of the channel near the Tailings Dam was also designed to contain the PMF with some erosion damage. Observations of the riprap since the original construction in 2000 have shown that the riprap is gradually weathering and breaking down. Test pits in 2014 confirmed that the in-place riprap is undersized compared to the original design (KCB 2015a). Observations show that the degradation of the riprap is happening slowly, and the channel could still convey large flood flows, though not to the level of the original design. There is the potential for an extreme flood event to initiate erosion of the channel. Part of the channel is located approximately 10 m from the Tailings Dam, and erosion in this area, if left unchecked, could eventually erode the glacial till soils in the right bank and undermine the dam toe. The channel is inspected twice per year and after large precipitation events, so this risk is appropriately managed through surveillance and maintenance that are carried out as per the OMS Manual. However, a long-term solution remains the recommendation, first made in 2014, for Teck to re-establish erosion protection. An options assessment and conceptual design was completed in 2020 for upgrading the channel to meet erosion protection requirements (KCB 2020a). An additional study is planned to investigate the option of a natural channel design that relies on bed material transport and vegetated banks to control erosion, instead of riprap.

#### *Recommendation/Action:*

*Select one or two preferred options for upgrading/replacing the existing Ed Creek Diversion Channel that will be advanced to a feasibility level design.*



Vegetation should be cleared periodically from the water conveyance structures including the Closure Spillway, Ed Creek Diversion Channel, and ditches or they will not operate to design capacity. This is covered under the vegetation management plan (Spectrum 2017).

## 5.6 Operational Performance

The Pinchi Lake Mine TSF has been closed for about 40 years and, as indicated in Section 2, there are no operational requirements.

## 5.7 OMS Manual and EPRP Review

The OMS Manual and the Emergency Preparedness and Response Plan (EPRP) for the Pinchi Lake Mine TSF were revised in 2019 (KCB 2019a). Later, the EPRP for the TSF was incorporated into the site-wide Mine Emergency Response Plan (Teck 2020). This means that there is currently duplication in the documentation of emergency response for the TSF.

### *Recommendation/Action:*

*The OMS Manual should be updated to reference the Mine Emergency Response Plan.*

## 6 CONCLUSIONS AND RECOMMENDATIONS

The deficiencies and recommendations from previous years and from the 2020 inspection are summarized in Table 6.1. The priorities assigned to each item in Table 6.1 are based on priority ratings developed by Teck (and consistent with HSRC) as follows:

- Priority 1 A high probability or actual dam safety issue considered immediately dangerous to life, health or the environment, or a significant risk of regulatory enforcement.
- Priority 2 If not corrected could likely result in dam safety issues leading to injury, environmental impact or significant regulatory enforcement; or a repetitive deficiency that demonstrates a systematic breakdown of procedures.
- Priority 3 Single occurrences of deficiencies or non-conformances that alone would not be expected to result in dam safety issues.
- Priority 4 Best Management Practice as a suggestion for continuous improvement towards industry best practices that could further reduce potential risks.

Notwithstanding the deteriorating riprap in the Ed Creek Diversion Channel, which has both an interim and longer term remedial plan, the Pinchi Lake Mine TSF appears to be in good condition and there are no major concerns related to dam safety.

Inspections were carried out in October 2019 and May 2020 by the Site Surveillance Officer, and in August 2020 by the Engineer of Record.

There were no threshold exceedances in the piezometers in 2020.

The riprap along the Ed Creek Diversion Channel is undersized and is gradually weathering and breaking down. This has reduced the capacity of the channel to convey large flood flows without erosion damage compared to the original design. Part of the channel is located approximately 10 m from the Tailings Dam, and erosion in this area, if left unchecked, could eventually erode the glacial till soils in the right bank and undermine the dam toe. The channel is inspected twice per year and after large precipitation events, so this risk is appropriately managed through surveillance and maintenance that are carried out as per the OMS Manual.

Climate data from the nearest climate station from Sep. 1, 2019 to Aug. 31, 2020 showed temperatures and precipitation were close to average conditions (based on 1981 to 2010 climate normals). Since the water balance is based on annual average climate data, there is no water storage in the TSF, and inflows are limited to direct precipitation and stormwater runoff from upslope, updating the water balance on an annual basis is deemed to be unnecessary.

The downstream consequence classification of the TSF was reviewed in 2012 after the completion of the reclamation/closure works, and the dam was classified as Significant. This classification review included a simplified dam breach assessment, but it did not evaluate the credibility of the failure modes considered. A failure modes evaluation should be completed to determine whether there are any credible failure modes, and if so, would they result in uncontrolled release of tailings and water.

The OMS Manual, which includes the EPRP as an appendix, was updated in 2019. The EPRP has since been incorporated into the site-wide Mine Emergency Response Plan (MERP), and the OMS Manual should be updated to reference the MERP.

**Table 6.1 Summary of Deficiencies and Recommendations**

Structure	ID No.	Deficiency or Non Conformance	Applicable Regulation or OMS Reference	Recommended Action	Priority	Recommended Deadline/Status
<b>Previous Recommendations Ongoing</b>						
TSF	2019-01	The dam breach assessment performed in 2012 did not specifically assess potential consequences related to the on-site residence.	HSRC	The dam breach assessment should be updated to meet current state of practice.	3	The residents have moved offsite. Dam breach assessment to be conducted if required after 2020-01 is completed.
Ed Creek Diversion Channel	2019-02	The riprap along the Ed Creek Diversion Channel is undersized and is deteriorating due to weathering.	OMS Manual	An options assessment and conceptual design should be completed for upgrading the channel to meet erosion protection requirements. Since failure of the riprap would not immediately affect the dam, the risk to the dam in the interim is effectively managed through inspections and maintenance as per the OMS Manual, and there is no immediate concern for dam safety.	3	Initial options assessment complete. Additional options are being considered and will be assessed in 2021.
<b>2020 Recommendations</b>						
TSF	2020-01	The dam breach assessment performed in 2012 did not assess the credibility of the failure modes considered.	HSRC	A failure modes evaluation should be completed to determine whether there are any credible failure modes, and if so, would they result in uncontrolled release of tailings and water.	3	End of 2021
Ed Creek Diversion Channel	2020-02	The riprap along the Ed Creek Diversion Channel is undersized and is deteriorating due to weathering	OMS Manual	Select one or two preferred options for upgrading/replacing the existing Ed Creek Diversion Channel that will be advanced to a feasibility level design.	3	Q3 2022
TSF	2020-03	The OMS Manual includes a superseded version of the EPRP as an appendix.	HSRC	The OMS Manual should be updated to reference the Mine Emergency Response Plan.	3	End of 2021

## 7 CLOSING

We thank you for the opportunity to work on this project. Should you have any questions, please do not hesitate to contact the undersigned.

**KLOHN CRIPPEN BERGER LTD.**



Daniel Klassen, P.Eng.  
Project Manager



Robert W. Chambers, P.Eng.  
Senior Geotechnical Engineer, Principal

## REFERENCES

- Azimuth. 2018. "Pinchi Mercury Mine: Surface Water Quality Monitoring 2017". March.
- Canadian Dam Association (CDA). 2007. "Dam Safety Guidelines 2007".
- Canadian Dam Association (CDA). 2013. "Dam Safety Guidelines 2007 (Revised 2013)".
- Canadian Dam Association (CDA). 2014. "Technical Bulletin: Application of Dam Safety Guidelines to Mining Dams".
- Hynes-Griffin M. E. and Franklin A. G. 1984. "Rationalizing the Seismic Coefficient Method". US Army Corps of Engineers. July.
- Klohn Crippen Berger (KCB). 2009a. "Pinchi Lake Tailings Facility – 2008 Annual Review", May 6.
- Klohn Crippen Berger (KCB). 2009b. "Pinchi Lake Mine Tailings Facility - Closure Spillway Design", July 3.
- Klohn Crippen Berger (KCB). 2012. "Pinchi Lake Mine Post-Reclamation Monitoring Requirements", April 20.
- Klohn Crippen Berger (KCB). 2015a. "Pinchi Lake Mine Tailings Storage Facility – 2014 Site Investigation and Maintenance", February 24.
- Klohn Crippen Berger (KCB). 2015b. "Pinchi Lake Mine Tailings Storage Facility – Response to MEM Memorandum dated February 3, 2015", June 30.
- Klohn Crippen Berger (KCB). 2017a. "Pinchi Lake Mine Tailings Storage Facility – 2016 Dam Safety Inspection", February 9.
- Klohn Crippen Berger (KCB). 2017b. "Pinchi Lake Mine – TSF Stability Assessment", November 17.
- Klohn Crippen Berger (KCB). 2017c. "Pinchi Lake Mine Tailings Storage Facility – 2016 Foundation Investigation", December 20.
- Klohn Crippen Berger (KCB). 2019a. "Operation, Maintenance and Surveillance Manual & Emergency Preparedness and Response Plan", March 19.
- Klohn Crippen Berger (KCB). 2019b. "Pinchi Lake Mine – TSF Closure Spillway Assessment – Draft Rev. 2", August 29.
- Klohn Crippen Berger (KCB). 2020a. "Pinchi Lake Mine – Ed Creek Diversion Channel Review and Options Assessment", September 11.
- Klohn Crippen Berger (KCB). 2020b. "Pinchi Lake Mine Tailings Storage Facilities – 2019 Seismic Hazard Assessment", September 21.
- Ministry of Energy and Mines (MEM). 2016. "Guidance Document – Health, Safety and Reclamation Code for Mines in British Columbia", July 20.

Ministry of Energy and Mines (MEM). 2017. "Health, Safety and Reclamation Code for Mines in British Columbia", February 28.

SNC Lavalin (SNC). 2018. "Annual Report – 2017 Groundwater Monitoring and Sampling Programs". March 7.

Spectrum Resource Group Inc. (Spectrum). 2017. "Pinchi Lake Mine – Site Integrated Vegetation Management Plan." December 12.

Teck Resources Ltd. (Teck). 2019. "Guideline for Tailings and Water Related Structures", January.


Teck Resources Ltd. (Teck). 2020. "Pinchi Lake Mine – Emergency Response Plan", March 31.

## FIGURES

---



Time: 11:24:47  
Date: 11/5/2020  
Scale: 1:2,5849(P5)  
Drawing File: Z:\W\CR\W07728A36-TML-Pinchi Lake 2020 Services\400 Drawings\CAD\05-FIGURES\2020 ANNUAL INSPECTION\Fig1.1 - MineSitePlan.dwg (thawker)  
Xref File(s): Z:\W\CR\W07728A36-TML-Pinchi Lake 2020 Services\400 Drawings\CAD\05-FIGURES\2020 ANNUAL INSPECTION\Fig1.1 - MineSitePlan.dwg (thawker)  
Image File(s): Pinchi-2013-20cm\_R



## LEGEND

-  PROPERTY BOUNDARY
-  WASTE ROCK DUMP

## NOTES

- ORTHOPHOTO IMAGE TAKEN IN 2013 (PROVIDED BY TECK).
- NAD83, UTM ZONE 10.

NOT FOR CONSTRUCTION

TO BE READ WITH KLOHN CRIPPEN BERGER REPORT DATED NOVEMBER 2020

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

CLIENT




PROJECT PINCHE LAKE MINE TSF 2020 ANNUAL SUMMARY OF TAILINGS FACILITY PERFORMANCE	
TITLE MINE SITE PLAN	
PROJECT No. M07728 A36	FIG. No. 1.1






KCB-R-MLB



Time: 11:19:51  
Date: 11/15/2020  
Scale: 1:2,584.9 (PS)  
Drawing File: Z:\M\VR\M07728A36-TML-Pinchi Lake 2020 Services\400 Drawings\CAD\05-FIGURES\2020 ANNUAL INSPECTION\Fig1.2 - TSF-Plan.dwg (hawker)  
Xref File(s): BM-Pinchi-10July13\_ACAD-Pinchi\_Lake\_407700E\_6053000Nv12  
Image File(s):



Time: 11:22:00  
Date: 11/15/2020  
Scale: 1:2,584 (PS)  
Drawing File: Z:\M\WOR\M07728A36-TML-Pinchi Lake 2020 Services\400 Drawings\CAD\05-FIGURES\2020 ANNUAL INSPECTION\Fig1.3 - Sections.dwg (trowker)  
Xref File(s):  
Image File(s): Teckcominco-color-logo



DAM HEIGHT AND SLOPE			OVERALL SLOPE (NOTE 2)
SECTION	DAM HEIGHT (m)	SLOPE OF D/S FACE	
A	14.0	2.7H:1V	2.7H:1V
B	2.5	2.7H:1V	2.4H:1V
C	1.8	2.3H:1V	4.5H:1V
D	1.5	2.0H:1V	4.3H:1V
E	1.8	4.3H:1V	4.3H:1V

#### LEGEND:

- PIEZOMETER TIP/SCREEN
- 732.1  
AUGUST 12, 2020 READING (m)
- ORIGINAL GROUND SURFACE PRE-1967
- GROUND SURFACE AFTER 2010/11 RECLAMATION/CLOSURE WORKS (SEP. 2012 LIDAR SURVEY)

#### NOTES:

1. ORIGINAL GROUND SURFACE HAS BEEN EXTRACTED FROM DWG. PLM-D-3, REV.1 AND IS APPROXIMATE.
2. OVERALL SLOPE IS MEASURED FROM DOWNSTREAM EDGE OF DAM CREST TO TOE OF NATURAL GROUND SLOPE (SECTIONS A AND B), TOE OF BORROW PIT SLOPE (SECTIONS C AND D) OR BASE OF ED CREEK DIVERSION CHANNEL (SECTION E).

NOT FOR CONSTRUCTION


TO BE READ WITH KLOHN CRIPPEN BERGER REPORT DATED NOVEMBER 2020

SCALE 0 10 m

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.	CLIENT <b>Teck</b> <b>Klohn Crippen Berger</b>	PROJECT PINCHI LAKE MINE TSF 2020 ANNUAL SUMMARY OF TAILINGS FACILITY PERFORMANCE	
		TITLE TAILINGS STORAGE FACILITY DAM CROSS SECTIONS	
PROJECT No. M07728 A36		FIG. No. 1.3	

KCB-R-MLB





LEGEND

ESL: Emergency Spills Lagoon




③ Observation Location

Not to Scale

NOTES:

1. All Locations shown are approximate.

<small>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</small>	CLIENT		PROJECT	
			PINCHI LAKE MINE TSF - 2020 ANNUAL SUMMARY OF TAILINGS FACILITY PERFORMANCE	
			TITLE	
			AUGUST 2020 OBSERVATION LOCATIONS	
	PROJECT No.		M07728A36	FIG No.
				4.1



AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

CLIENT

**Teck**

**Klohn Crippen Berger**

PROJECT PINCHI LAKE MINE TSF - 2020 ANNUAL  
SUMMARY OF TAILINGS FACILITY PERFORMANCE

TITLE

PIEZOMETER READINGS

PROJECT No. M07728A36

FIG No. 4.2

## **APPENDIX I**

### **Facility Data Sheet**

---

## Appendix I Facility Data Sheet

### PINCHI LAKE MINE TSF DAM

#### PHYSICAL DESCRIPTION

Dam Type	Earthfill
Maximum Dam Height	15 m
Dam Length	1300 m
Dam Crest Width	6 m to 8 m May be wider in some areas.
Impoundment Area	21 ha (surface area of covered tailings)
Volume of Tailings	1 million m <sup>3</sup> approximate
Reservoir Capacity	This is a “dry” tailings impoundment. There is no storage of water and the impoundment is normally dry.
Consequence Classification	Significant
Inflow Design Flood (IDF)	1/3 between 1/1000 and PMF (based on consequence classification of Significant)
Design Earthquake	1/2475 annual exceedance probability (based on consequence classification of Significant)
Spillway Capacity	Spillway has capacity to route IDF with > 4 m freeboard in the impoundment, and 0.5 m in the spillway channel. However, riprap from the dam toe to the downstream end of the channel is undersized for the IDF and may be damaged. Estimated peak spillway discharge = 7 m <sup>3</sup> /s
Catchment Area	55 ha
Access to Dam	Vehicle access to the mine from Fort St. James is 25 km north along Germansen Road, and then 20 km west along Pinchi Lake Road. Both roads are gravel surfaced. The access road into the mine site is gated. The mine site can also be reached by water over Pinchi Lake. The lake usually has ice cover from November to mid-April.

## **APPENDIX II**

### **August 2020 Photographs**

---



## Appendix II August 2020 Photographs

**Photo II-1** Tailings Dam – east leg, looking south. Note vegetation.



**Photo II-2** Tailings Dam – Pond near toe of east leg.





**Photo II-3      Tailings Dam – East leg looking north from toe.**



**Photo II-4      Tailings Dam – East leg, looking north.**





**Photo II-5      Tailings Dam – East leg, looking west at the covered tailings surface**



**Photo II-6      Tailings Dam – South leg, looking east**





**Photo II-7      Tailings Dam – South leg, looking north at the covered tailings surface.**




**Photo II-8      Tailings Dam – South leg, looking west.**





**Photo II-9** Tailings Dam – Southwest leg, looking northwest along the crest.



**Photo II-10** Tailings Dam – Southwest leg, looking southeast along downstream slope.





**Photo II-11 Tailings Dam – Southwest leg, looking downstream from the crest.**



**Photo II-12 Tailings Dam – Southwest leg, looking northwest along the downstream slope.**






**Photo II-13** Tailings Dam – West leg, looking south along downstream slope.



**Photo II-14** Tailings Dam – West leg, looking north along upstream slope.





**Photo II-15** Tailings Dam – West leg, looking north along crest.



**Photo II-16** Closure Spillway – Inlet apron.





**Photo II-17 Closure Spillway – Inlet apron.**



**Photo II-18 Closure Spillway - Inlet**





**Photo II-19 Closure Spillway – looking downstream from dam crest.**



**Photo II-20 Spillway inlet looking downstream.**





**Photo II-21 Closure Spillway – looking downstream.**



**Photo II-22 Closure Spillway – looking downstream towards outlet. Note vegetation.**





**Photo II-23     Closure Spillway – Head scarp of slump above right bank**



**Photo II-24     Closure spillway – Pond at downstream end of riprap**





**Photo II-25 Spillway Downstream Channel – Middle Reach, looking upstream from near culvert beneath road to on-site residence.**



**Photo II-26 Spillway Downstream Channel – Outlet of culvert beneath road to on-site residence.**





**Photo II-27     Spillway Downstream Channel – Lower Reach, looking downstream.**



**Photo II-28     Borrow Area A – Looking west from access road.**





**Photo II-29    Borrow Area A – crack monitoring rod location 103 (crack not visible).**



**Photo II-30    Borrow Area A – Looking east along the slope.**





**Photo II-31 Borrow Area A – Wet ground in northeast corner.**



**Photo II-32 Borrow Area A – New crack identified in northeast corner.**





**Photo II-33 Borrow Area A - Looking west along the slope.**



**Photo II-34 Ed Creek Diversion Channel – Looking downstream towards outlet at Pinchi Lake.**





**Photo II-35** Ed Creek Diversion Channel – Riprap on right bank, showing weathering and breakage.



**Photo II-36** Ed Creek Diversion Channel – looking upstream from between third bends and outlet.





**Photo II-37 Ed Creek Diversion Channel – looking downstream from between second and third bends.**



**Photo II-38 Ed Creek Diversion Channel – Flow at base of channel.**





**Photo II-39** Ed Creek Diversion Channel – looking upstream from near second bend. Light coloured area of riprap was replaced in 2014 and is in good condition.



**Photo II-40** Ed Creek Diversion Channel – looking downstream from between first and second bends.





**Photo II-41**    **Ed Creek Diversion Channel – looking upstream from between first and second bends.**



**Photo II-42**    **Ed Creek Diversion Channel – Looking downstream from near first bend.**





**Photo II-43**    Ed Creek Diversion Channel – Looking downstream from first bend.



**Photo II-44**    Ed Creek Diversion Channel – Looking upstream towards inlet.





**Photo II-45** Inlet of 460 mm culvert on north bank of Ed Creek Diversion Channel. There is minor vegetation upstream of the inlet.



**Photo II-46** Outlet of 460 mm culvert on north bank of Ed Creek Diversion Channel.





**Photo II-47** Inlet of Ed Creek culverts under Pinchi Lake Road. Note only one culvert is flowing.



**Photo II-48** Looking upstream from inlet of Ed Creek culverts under Pinchi Lake Road.





**Photo II-49** Looking east from near upstream end of Ed Creek culverts under Pinchi Lake Rd. Note new ditch excavated along the road.



**Photo II-50** Outlet of Ed Creek culverts under Pinchi Lake Road. Note only one culvert is flowing.



## **APPENDIX III**

### **August 2020 Inspection Forms**

---

1. Tailings Dam and Tailings Impoundment
2. Closure Spillway
3. Spillway Downstream Channel
4. Road Ditch Above Tailings Impoundment
5. Borrow Area A
6. Ed Creek Diversion Channel
7. Ed Creek Culverts at Pinchi Lake Road

**Pinchi Lake Mine Tailings Storage Facility  
Inspection Checklist**

**TAILINGS DAM AND TAILINGS IMPOUNDMENT**

Date: August 12, 2020

Inspected By: D. Klassen, B. Chambers

Time: 9 am to 12 pm

Pond Water Level: No standing water

Weather: Cloudy, light showers, windy periods, 12°

Is there any apparent .....	Yes	No	Comments
<b>Cracks</b>			
• Embankment cracks on the dam crest?		X	
○ Enlargement of cracks or new cracks in SW leg and S leg of dam (first observed in 2015)?		X	Not visible, see comment 1
• Embankment cracks on the u/s slope?		X	
• Embankment cracks on the d/s slope?		X	
<b>Vegetation Growth and Debris</b>			
• Excessive tree or shrub growth on embankment?		X	
• Debris in tailings impoundment?		X	
<b>Other Structural Problem</b>			
• Settlement or erosion on the dam crest?		X	
• Slough, slides, bulges or erosion on u/s slope of dam?		X	
• Slough, slides, bulges or erosion on d/s slope of dam?		X	
• Sinkhole on dam crest?		X	
• Sinkhole on u/s slope of dam?		X	
• Sinkhole on d/s slope of dam?		X	
• Sinkhole in tailings pond till cover?		X	
• Erosion of flow channels in tailings pond till cover?		X	
<b>Ponding / Seepage</b>			
• Evidence of water ponding on dam crest?		X	
• Wet areas or seepage on d/s slope or toe of dam?		X	
• Evidence of water ponding at d/s toe of dam?	X		See comment 2 below
• Wet areas or seepage along d/s abutments?		X	
<b>Animal Activity</b>			
• Rodent burrows in dam embankment?		X	
• Beaver dam in Tailings Pond?		X	

Additional comments:

- Cracks have been observed in this area for several years and are believed to be formed by loosening and drying of the soil as part of the reclamation and seeding, and are not considered to be a dam safety issue. These cracks were not visible during the 2020 inspection.
- A pond is located near the toe of the east leg of the dam, which drains to the south through a culvert into Ed Creek Diversion Channel. This pond has been observed in previous inspections and appears to be related to local runoff. No other ponds were observed near the dam toe.

**Pinchi Lake Mine Tailings Storage Facility  
Inspection Checklist**

**CLOSURE SPILLWAY**

Date: August 12, 2020

Inspected By: D. Klassen, B. Chambers

Time: 10 am

Weather: Cloudy, 12°

Is the spillway flowing? No (yes / no)

If yes, give approx. flow depth: \_\_\_\_\_ mm

Is the flow above the riprap? No (yes / no)

If yes, give approx. flow depth above riprap:  
\_\_\_\_\_ mm

Is there any apparent .....	Yes	No	Comments
<b>Vegetation Growth and Debris</b>			
• Excessive tree or shrub growth along the channel?		X	A few small shrubs
• Debris in the channel?		X	
<b>Riprap</b>			
• Displaced or broken down riprap in channel bottom?		X	
• Displaced or broken down riprap along the right bank?		X	
• Displaced or broken down riprap along the left bank?		X	
<b>Erosion, cracks, slough, slides or bulges</b>			
• Along the bottom of channel?		X	
• Along the right bank of channel?		X	
○ Any signs of recent movement of slump on right bank?		X	Appears unchanged from previous inspections
• Along the left bank of channel?		X	
<b>Seepage</b>			
• Seepage into the channel from right side slope?		X	
• Seepage into the channel from left side slope?		X	
<b>Animal Activity</b>			
• Beaver dam in spillway channel?		X	
• Any other animal activity?		X	

NOTE: left and right banks are looking downstream along the channel.

Additional comments:

30 cm deep pond at the downstream end of the spillway. No flow.



**Pinchi Lake Mine Tailings Storage Facility  
Inspection Checklist**

**SPILLWAY DOWNSTREAM CHANNEL**

Date: August 11, 2020

Inspected By: D. Klassen

Time: 3 pm

Weather: Partly cloudy, 13°C

Is there flow in the channel? No (yes / no)

Give location of flow: \_\_\_\_\_

Give approx. flow depth: \_\_\_\_\_ mm

Is there any apparent .....	Yes	No	Comments
<b>Middle Reach*</b>			
• Debris in the channel?		X	
• Erosion in the channel?		X	
• Beaver activity in channel?		X	
<b>Culvert under Road to Caretaker's Residence</b>			
• Blockage of culvert inlet or outlet?	X		Grass is growing in front of inlet, partially blocking it.
• Structural damage or deformation of culvert pipe?		X	
• Displaced or broken-down riprap?		X	
<b>Lower Reach (along former Emergency Spills Lagoon)</b>			
• Excessive tree or shrub growth in the channel?		X	
• Debris in the channel?		X	
• Erosion in the channel?		X	
• Displaced or broken-down riprap in channel?		X	
• Beaver activity in channel?		X	

\*NOTE: Middle reach of Spillway Downstream Channel is the flow route from the end of the riprap lined Closure Spillway channel to the culvert under the road to the Caretaker's residence.

**Additional comments:**

- Only the upper and lower ends of the middle reach of the Spillway Downstream Channel were inspected. This reach follows natural channels, and has dense tree and bush growth and debris such as windfalls.
- Water ponding locally at the outlet, 5 cm above the invert of the culvert, and 8 cm deep immediately downstream of the culvert. The channel downstream of this is dry until it reaches the lake.

**Pinchi Lake Mine Tailings Storage Facility  
Inspection Checklist**

**ROAD DITCH ABOVE TAILINGS IMPOUNDMENT**

Date: August 12, 2020

Inspected By: D. Klassen, B. Chambers

Time: 12:00 pm

Weather: Cloudy, drizzling, 12°C

Is there flow in the channel? No (yes / no)

Give location of flow: \_\_\_\_\_

Give approx. flow depth: \_\_\_\_\_ mm

Is there any apparent .....	Yes	No	Comments
<b>Road Ditch</b>			
• Excessive tree or shrub growth in the channel?	X		Trees growing in ditch near bottom of hill close to the mine gate
• Debris in the channel?		X	
• Erosion in the channel?		X	
• Beaver activity in the channel?		X	

Additional comments:

---

---

---

---

---

---

---

**Pinchi Lake Mine Tailings Storage Facility  
Inspection Checklist**

**BORROW AREA A**

Date: August 12, 2020

Inspected By: D. Klassen, B. Chambers

Time: 10:30 am

Weather: Cloudy, 12°C

Is there any apparent .....	Yes	No	Comments
<b>Cracks</b>			
• Cracks on ground between borrow pit and toe of dam?		X	
• Cracks on borrow pit slope?	X		See comment 1 below
<b>Other Structural Problems</b>			
• Sloughs, slides, bulges or erosion on borrow pit slope?		X	
<b>Ponding / Seepage</b>			
• Wet areas or seepage on borrow pit slope?		X	
• Wet areas or seepage at toe of borrow pit slope?	X		See comment 2 below
• Evidence of water ponding within borrow area?		X	
<b>Animal Activity</b>			
• Rodent burrows in borrow pit slope?		X	

**Additional comments:**

- Newly discovered cracks were observed in northeast corner of the borrow pit, up to 2 cm wide and 10 cm deep, located about 20 m east of the eastern set of crack monitoring rods (#403). Previously observed cracks to the west of this have filled in with vegetation and have not been clearly visible for several years.
- A few small areas of wet ground were observed between the northeast corner of the borrow area and 50 m to the west. No ponds larger than a few centimetres were observed, and there was no flowing water.



**Pinchi Lake Mine Tailings Storage Facility  
Inspection Checklist**

**ED CREEK DIVERSION CHANNEL**

Date: August 12, 2020

Inspected By: D. Klassen, B. Chambers

Time: 11 am

Weather: Cloudy, 12°C

Is there flow in the channel? Yes (yes / no)

Give location of flow: Base of channel Give approx. flow depth: 200 mm

Is there any apparent .....	Yes	No	Comments
<b>Vegetation Growth and Debris</b>			
• Excessive tree or shrub growth along the channel?		X	See comment 1 below
• Debris in the channel?		X	
<b>Riprap</b>			
• Displaced or broken down riprap in channel bottom?	X		See comment 2 below
• Displaced or broken down riprap along the right bank?	X		See comment 2 below
• Displaced or broken down riprap along the left bank?	X		See comment 2 below
<b>Erosion, cracks, slough, slides or bulges</b>			
• Along the bottom of channel?		X	
• Along the right bank of channel?		X	
• Along the left bank of channel?		X	
<b>Seepage</b>			
• Seepage into the channel from right side slope?		X	
• Seepage into the channel from left side slope?		X	
<b>Animal Activity</b>			
• Beaver dam in spillway channel?		X	
• Any other animal activity?		X	

NOTE: left and right banks are looking downstream along the channel.

Additional comments:

1. Vegetation was observed throughout the base of the channel, including tall grasses and some bushes, but it was not excessive.
2. As noted during previous inspections, riprap along entire diversion channel is deteriorating. Visual inspection suggested there were no significant changes from the condition in recent years.

**Pinchi Lake Mine Tailings Storage Facility  
Inspection Checklist**

**ED CREEK CULVERTS AT PINCHI LAKE ROAD**

Date: August 12, 2020

Inspected By: D. Klassen, B. Chambers

Time: 8 am

Weather: Cloudy, 12°C

Is there flow in the culverts? Yes (yes / no)

Give approx. water depth in channel at culvert inlet: 70 mm

Is there any apparent .....	Yes	No	Comments
<b>Culverts Under Pinchi Lake Road</b>			
• Excessive tree or shrub growth at inlet or outlet?		X	
• Blockage of culvert inlets or outlets?		X	
• Structural damage or deformation of culvert pipe?		X	
• Erosion in channel u/s or d/s of culvert?		X	
• Beaver activity in Ed Creek u/s or d/s of culvert?		X	

Additional comments:

Only east culvert is flowing

---

---

---

---

---

## **APPENDIX IV**

### **1975 Tailings Dam Drawing**

---

Dwg. PLM-D-514, Rev.0 – Tailings Dam Extension 1975 – Plan & Sections





## **APPENDIX V**

### **Water Balance**

---

September 10, 2019

Teck Metals Ltd.  
Kimberley Operations  
Bag 2000  
Kimberley, BC  
V1A 3E1

**Ms. Michelle Unger**  
**Mine Manager**

Dear Ms. Unger:

**Pinchi Lake Mine Tailings Storage Facility**  
**Water Balance**

## **1 INTRODUCTION**

This letter summarizes an update to the water balance completed by Klohn Crippen Berger Ltd. (KCB) in 2009 for the Pinchi Lake Mine Tailings Storage Facility (TSF).

The Pinchi Lake Mine TSF is located in central British Columbia, on the north side of Pinchi Lake, at an elevation of approximately 750 m. No tailings have been deposited in the facility since 1975 and closure reclamation works were completed in 2011.

## **2 METHODOLOGY**

The previous Pinchi Lake Mine TSF water balance (KCB 2009) included a small (0.4 ha) pond near the outlet of the TSF where water levels and discharge (through a decant structure) had been measured since 1997. The last year of measurement at the TSF outlet occurred in 2008, just prior to reclamation and closure of the TSF that saw: the pond drained; the decant structure and emergency spillway replaced with the current riprap closure spillway; and the tailings covered with glacial till and vegetated.

The water balance was modelled in GoldSim® as a single catchment area reporting to the spillway. Snow accumulation and snowmelt were estimated using daily precipitation and temperature data. Snow accumulation was validated using regional snow course data. Runoff, seepage loss and evaporation loss in the catchment were estimated using a soil moisture accounting (SMA) model<sup>1</sup>.

---

<sup>1</sup> A model that uses daily precipitation, temperature, soil moisture, and soil permeability of a catchment to estimate the amount of water that enters, is stored in, and leaves the catchment.



The surface soil storage and seepage rate were calibrated to water level and flow measurements taken in 2007 and 2008 (assuming the small pond present in 2008), or the “pre-cover scenario”.


For this 2019 assessment, the GoldSim model was updated to reflect current closure conditions, or the “post-cover scenario”, by removing the free water pond and increasing soil storage to account for the vegetated glacial till closure cover. The updated model was then run using the past 20 years of climate data (1998 to 2017) to estimate monthly average flows. Modelled runoff volumes in April and May were compared to estimated runoff volumes from flow measurements in 2011 and 2012 to provide a level of confidence in the results. However, there is not enough data to calibrate the post-cover scenario.

## 2.1 Input Data

### 2.1.1 Catchment Areas

Approximately 22.0 ha of past tailings deposition area and 11.3 ha of upstream catchment report to the closure spillway (Figure 2.1). The upstream catchment assumes the ditch beside the access road operates during normal conditions. Note that this upstream catchment area is less than what was used in the assessment of the TSF spillway capacity because that assessment assumed the road upstream of the TSF is breached during the Inflow Design Flood (IDF).

**Figure 2.1 TSF Water Balance Catchment Areas**



### 2.1.2 Climate


Regional Environment Canada climate stations with parameters of interest, along with period of record and elevation, are listed in Table 2.1 and shown in Figure 2.2.

Snowpack and snowmelt are estimated based on precipitation and temperature data; however, measurements of snowpack are needed to validate these estimates. Snow course is measured in the spring at Burns Lake, 100 km southwest of site, at an elevation 820 m, similar to Pinchi TSF (750 m).

**Table 2.1 Regional Climate Stations**

Station Name	Station ID	Period of Record	Elevation (m)	Distance from Site	Parameters of Interest
Fort St James	1092970	1895 to 2018	691	20 km southeast	Precipitation, Temperature
Fort St James Auto	1092975	2013 to 2018	688	20 km southeast	Precipitation, Temperature
Vanderhoof	1098D90	1980 to 2018	638	70 km southeast	Precipitation, Temperature
Topley Landing	1078209	1962 to 2017	722	110 km northwest	Lake Evaporation
Burns Lake	1A16	1970 to 2018	820	100 km southwest	Snow Course

**Figure 2.2 Regional Climate Station Locations**



Note: Fort St. James and Fort St James Auto stations are in the same location on this map.

Precipitation and temperature are inputs to the Pinchi Lake TSF water balance. These parameters were taken first from the Fort St James station due its proximity to site, with gaps filled in with data from Vanderhoof. To account for Pinchi Lake TSF being at a higher elevation, precipitation data from these stations was increased by 3%<sup>2</sup> and temperature data was decreased by 0.3°C<sup>3</sup>.

Lake evaporation, or potential evapotranspiration (PET), is measured at Topley Landing from May to September and was used to estimate actual evapotranspiration (AET) losses from the pond and catchment.

Monthly averages of the 1998 to 2017 climate data inputs used in the GoldSim model are presented in Table 2.2.

**Table 2.2 1998 to 2017 Monthly Climate Averages**

Period	Precipitation (mm)	Rain <sup>1</sup> (mm)	Snow <sup>1</sup> (mm)	PET <sup>2</sup> (mm)
January	45	2	43	3
February	28	2	27	6
March	27	7	19	23
April	26	21	5	48
May	40	40	1	80
June	47	47	0	92
July	49	49	0	98
August	43	43	0	84
September	40	40	1	48
October	52	37	15	20
November	42	7	34	6
December	41	1	40	2
<b>Annual Totals</b>	<b>480</b>	<b>295</b>	<b>185</b>	<b>509</b>
<b>Percent of Precipitation</b>	<b>100%</b>	<b>62%</b>	<b>38%</b>	

Notes:

1. Estimated from precipitation data based on temperature.
2. PET is estimated from October to April, when data from Topley Landing is not available.

### 2.1.3 Surface Storage

Based on the recorded data, discharge from the TSF spillway normally occurs only during freshet indicating that there is enough surface depression, vegetation and upper soil moisture storage to contain most rain events. An initial estimate of these storages for the pre-cover model calibration (i.e., 2007/2008 condition) is 80 mm, broken down as follows:

- 65 mm of soil moisture storage in a dry antecedent moisture condition (AMC) based on:
  - ♦ 0.221 water content at wilting point (i.e. dry antecedent condition);
  - ♦ 0.430 water content at saturation point; and

<sup>2</sup> Based on an increase of 5% per 100 m elevation gain suggested by Quick (2005).

<sup>3</sup> Based on a decrease of 0.65°C per 100 m elevation gain, which is the average lapse rate defined for the International Standard Atmosphere.



- ♦ 300 mm thick surface soil layer involved in evapotranspiration processes (i.e., 300 mm capillary rise for a silty/clay soil type).
- 10 mm of surface depression storage, assumed on a permeable surface and mild grade; and
- 5 mm of vegetation storage (before the closure cover was installed).

Using the measured data from spring freshet events to calibrate the pre-cover Goldsim model, the total moisture storage for the TSF was estimated to be 90 mm (Section 2.2), compared to the initial estimate of 80 mm. A 90 mm storage is equivalent to a curve number of 74 under the Soil Conservation Service (SCS) TR-55 hydrology model, which is reasonable for a flat and permeable area.

For the post-cover water balance, surface storage was increased to 100 mm to account for the vegetated glacial till cover. This is approximately consistent with an SCS curve number of 72.

#### 2.1.4 Seepage Rate

Seepage is estimated as the amount of precipitation and/or snowmelt percolating into the tailings and reporting somewhere downstream of the spillway. In the 2009 water balance, a saturated hydraulic conductivity of  $1 \times 10^{-8}$  m/s, or approximately 1 mm/day, was used for the tailings. This value was not revised during pre-cover model calibration. The glacial till closure cover is assumed to have a hydraulic conductivity similar to the tailings, so no change to this value was made for the post-cover scenario.

## 2.2 Pre-Cover Scenario Calibration

Selection of the period for model calibration<sup>4</sup> was based on periods where there were concurrent data sets for pond level, discharge measurements in the TSF, and snow course measurements (at Burns Lake). This level of information was only available for the pre-cover scenario in 2007 and 2008. Results of the model calibration are presented in Figure 2.3.

The estimated snow accumulation snow water equivalent (SWE) from the calibrated water balance model is comparable to the snow course SWE measurements at Burns Lake in 2007 and 2008. Burns Lake is at a similar elevation to the Pinchi TSF, so no elevation correction was required.

The estimated water level and TSF discharges from the calibrated water balance model closely correlate to the measured data in 2007 and 2008. The model predicted some discharge in late fall in both years when measurements were not taken; however, these volumes were small compared to the freshet discharge volumes.


The results described above and shown in Figure 2.3 indicate that the calibrated water balance model provides a reasonable representation of the hydrologic performance of the Pinchi TSF.

---


<sup>4</sup> Calibration included adjusting watershed storage, seepage and evaporation input parameters to fit measured pond level and flow data. Modelled snow accumulation was compared to measured values at Burns Lake, but no snowmelt parameters were adjusted.

**Figure 2.3 Pre-Cover Model Calibration using 2007 and 2008 Data**


### Climate Inputs



### Snowpack



### Pond Level and Discharge Calibration



## 2.3 Post-Cover Scenario Validation

The post-cover scenario was validated<sup>5</sup> using flow rates measured<sup>6</sup> approximately 450 m downstream of the TSF spillway. In 2011 and 2012, flows were measured five and four times, respectively; however, in 2013 to 2019, flows were measured either once or twice a year. Due to the higher number of measurements in 2011 and 2012, this period was selected for validation of the post-cover scenario model. Flow measurements and the associated runoff volume estimated for April-May in 2011 and 2012 are compared with modelled April-May runoff volumes in Table 2.3.

**Table 2.3 Post-Cover Model Validation using 2011 and 2012 Data**

Parameter	2011	2012
Flow Measurement 1	3.2 L/s on April 19	11.8 L/s on April 23
Flow Measurement 2	9.4 L/s on April 26	9.2 L/s on April 30
Flow Measurement 3	7.3 L/s on May 3	3.6 L/s on May 7
Flow Measurement 4	3.2 L/s on May 10	0.9 L/s on May 14
Flow Measurement 5	0 L/s on May 17	n/a
Measured April-May Runoff Total <sup>1</sup>	10,500 m <sup>3</sup>	11,000 m <sup>3</sup>
Modelled April-May Runoff Total	8,300 m <sup>3</sup>	9,400 m <sup>3</sup>

Note:

1. Total April-May runoff volumes were estimated based on the measured flow rates and estimated flow durations.

The estimated measured runoff volume is between 15% and 25% higher than the modelled April-May runoff volumes in 2011 and 2012. This difference is likely due to the increase in catchment area between the TSF outlet and the location of the measurements. This comparison indicates that the post-closure scenario model is a reasonable representation of the conditions and that no further calibration of the model is needed.

## 3 RESULTS

The estimated average monthly TSF water balance<sup>7</sup> results reflecting the current (2018) post-cover closure conditions, with no free water pond and a vegetated glacial till cover, are summarized in Table 3.1. The table also includes annual totals for 2017<sup>(8)</sup> for comparison purposes.

An estimated 10% of direct precipitation on the TSF is lost to seepage, while 80% is lost to AET on an average annual basis. Average spillway discharge is the remaining 10% of direct precipitation on the TSF plus runoff from the upstream catchment.

<sup>5</sup> Validation included to comparing modelled April and May runoff volumes for the post-cover scenario to measured data in 2011 and 2012, without the adjustment of any input parameters.

<sup>6</sup> Collected by Ecofor in April and May between 2011 and 2019.

<sup>7</sup> The post-closure water balance used climate data from 1998 to 2017.

<sup>8</sup> 2017 totals reflect the period January 1, 2017 to December 31, 2017. This is different from the 2017 water year, which runs from October 1, 2016 to September 30, 2017.



**Table 3.1 Average and 2017 TSF Water Balance Results**

Period	TSF Inflows		TSF Outflows and Storage			
	Upstream Catchment Runoff (m³)	Rainfall and Snowmelt (m³)	AET (m³)	Seepage (m³)	Spillway Discharge (m³)	Change in Storage <sup>1</sup> (m³)
January	100	3,600	700	1,400	400	1,200
February	200	1,800	1,500	1,200	600	-1,300
March	1,000	13,900	6,000	1,900	3,000	4,000
April	3,300	19,800	12,600	3,100	9,800	-2,400
May	200	9,200	16,500	1,200	700	-9,000
June	0	10,400	11,900	0	0	-1,500
July	0	10,700	9,800	100	0	800
August	0	9,500	9,500	0	0	0
September	0	8,800	8,700	0	0	100
October	100	10,400	4,700	300	200	5,300
November	100	6,100	1,500	1,200	300	3,200
December	100	1,700	400	1,300	300	-200
<b>Average Annual Totals</b>	<b>5,100</b> <b>(0.2 L/s)</b>	<b>105,900</b> <b>(3.4 L/s)</b>	<b>83,800</b> <b>(2.7 L/s)</b>	<b>11,700</b> <b>(0.4 L/s)</b>	<b>15,300</b> <b>(0.5 L/s)</b>	<b>200</b> <b>(0.0 L/s)</b>
<b>2017 Totals</b>	<b>1,900</b> <b>(0.1 L/s)</b>	<b>82,200</b> <b>(2.6 L/s)</b>	<b>61,000</b> <b>(1.9 L/s)</b>	<b>17,600</b> <b>(0.6 L/s)</b>	<b>5,300</b> <b>(0.2 L/s)</b>	<b>200</b> <b>(0.0 L/s)</b>

Note:

1. Reflects water stored as pore water in the closure cover over the tailings or in depressions on the surface.

## 4 CLOSING


This letter is an instrument of service of Klohn Crippen Berger Ltd. The letter has been prepared for the exclusive use of Teck Metals Ltd. (Client) for the specific application to the Pinchi Lake Mine Tailings Storage Facility. The letter's contents may not be relied upon by any other party without the express written permission of Klohn Crippen Berger. In this report, Klohn Crippen Berger has endeavoured to comply with generally-accepted professional practice common to the local area. Klohn Crippen Berger makes no warranty, express or implied.


Yours truly,

**KLOHN CRIPPEN BERGER LTD.**

  
Stephen Clark, P.Eng., M.Eng.  
Water Resources Engineer



  
Daniel Klassen, P.Eng.  
Project Manager



SC:jc

## REFERENCES

Klohn Crippen Berger. 2009. "Pinchi Lake Tailings Facility: 2008 Annual Review". Prepared for Teck Cominco Metals Ltd., May 6.

Quick, M.C. 2005. "UBC Watershed Model: User's Manual". University of British Columbia.



## APPENDIX VI

### Quantifiable Performance Objectives

---

## Appendix VI

### Quantifiable Performance Objectives

Quantifiable Performance Objectives for the Pinchi Lake Mine Tailings Storage Facility are as follows.

#### VI-1 PIEZOMETERS

The threshold levels established for piezometers are based on stability analysis and are summarized in Table VI-1. Threshold level exceedances will be reviewed by the Engineer of Record, and further action will be advised based on subsequent engineering analysis.

**Table VI 1 Threshold Levels for Piezometers**

Piezometer ID	Serial	Threshold Value (Piezometric Elevation in metres)
DH16-01-VWP1	VW38610	736.1
DH16-01-VWP2	VW38611	736.1
DH16-02-VWP1	VW38608	738.5
DH16-02-VWP2	VW38609	738.5
DH16-03-VWP1	VW38606	737.0
DH16-03-VWP2	VW38607	737.0

#### VI-2 SURVEY MONUMENTS

Alert criteria for displacement of survey monuments on the dam are as follows:

- Vertical displacements over one year greater than 50 mm.
- Horizontal displacements over one year, perpendicular to the dam alignment, greater than 50 mm.
- An engineering assessment is required for a continuing trend of movement if cumulative displacements of the dam in a credible (i.e., plausible) direction exceed 100 mm, relative to the baseline readings.